

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:34 pm, Apr 26, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources, Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	432-425-2023
Facility Name	Vaca Ridge 30 SWD #1	Facility Type	Salt Water Disposal

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-025-28873
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	30	24S	34E	1980'	South	1980'	West	Lea

Latitude 32.186336 Longitude -103.51098

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	750	Volume Recovered	700			
Source of Release	Swedge on discharge water line	Date and Hour of Occurrence	4-24-2016	Date and Hour of Discovery	1200			
Was Immediate Notice Given?	If YES, To Whom? NA							
	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required							
By Whom?	NA	Date and Hour						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.							
	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No							



If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*

The release stayed on the pad. All fluids were recovered immediately by vac trucks except for an estimated 50 bbls. Third Party consultant will go out and delineate horizontal and vertical extent, then prepare work plan for remediation. Remediation will likely consist of dig and hauling the contaminated soils.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz	Approved by Environmental Specialist: 	
Title: Sr. Environmental Rep, EOG Resources, Inc.	Approval Date: 04/26/2016	Expiration Date: 06/26/2016
E-mail Address: zane.kurtz@eogresources.com	Conditions of Approval:	
Date: 4-26-2016 Phone: 432-425-2023	Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/approval.	
		Attached <input type="checkbox"/> IRP 4261

* Attach Additional Sheets If Necessary

nJXK1611755817
pJXK1611755960