

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:04 pm, May 04, 2016

Revised August 6, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Eva E Blinberry Federal Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-10937

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	34	23S	37E					Lea County, NM

Latitude N 32.26360° Longitude W 103.14557°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	1 bbl oil, 8 bbls produced water	Volume Recovered	0.5 bbl
Source of Release	Stress/fatigue of heater treater fire tube	Date and Hour of Occurrence	04/29/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	04/29/2016 @ 3:22 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Stress/Fatigue of the heater treater fire tube caused a spill of 1 bbl of oil and 8 bbls of produced water. A vacuum truck recovered 0.5 bbl of oil and the fire tube was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 60' x 15' both on and off location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 05/04/2016	Expiration Date: 07/04/2016
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/> IRP 4268
Date: 5-4-16 Phone: (575) 513-8289	Discrete samples only. Delineate and remediate per NMOCD guidelines.		

* Attach Additional Sheets If Necessary

n)XK1612554118
p)XK1612554211