District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Me Energy Minerals and Natur

RECEIVED
By JKeyes at 10:22 am, May 09, 2016

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505



## Release Notification and Corrective Action

						<b>OPERA</b>	ГOR		] Initia	l Report	$\boxtimes$	Final Report
Name of Co					Contact							
Yates Petrol	leum Corp	oration			Amber Griffin							
Address				Telephone No.								
105 S. 4 <sup>th</sup> Street Artesia, NM 88210						575-748-4111						
Facility Nar				Facility Type								
Undaunted 1	BSD State	Com #1H		Well & Tanks								
Surface Ow	ner		wner	API No.								
State State									30-025-40408			
State												
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/West Line		County		
0	2	25S	32E	175		South	2200	Ea	ıst	Lea		
<b>Latitude</b> 32.15266 <b>Longitude</b> 103.64366												
NATURE OF RELEASE												
Type of Rele			Volume of Release			Volume Recovered						
Produced Water Source of Release						25 B/PW Date and Hour of Occurrence			18 B/PW Date and Hour of Discovery			
Steel flow line						2/28/2016; AM 2/28/2016; AM					covery	
Was Immediate Notice Given?						If YES, To Whom?						
✓ Yes ☐ No ☐ Not Required												
						Mathew Hagman, Mark Naranjo, Dana Vackar Strang						
By Whom? Robert Asher						Date and Hour: 2/29/2016 8:32 AM via email						
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.						
			1 162 12									
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.*												
A steel water flow line developed a hole. The water flow line was isolated by closing upstream and downstream valves. The water pump was also turned												
off and the line was fixed. Vacuum trucks were called to recover released produced water. After further investigation of the steel line, it was determined that the line had been struck by a bullet of unknown caliber by an unknown individual. (The issue was reported to the Lea County Sheriff's Office).												
Describe Area Affected and Cleanup Action Taken:												
The affected	area is show	wn on the atta	ched Goog	gle Earth image; a			water was contain					
							cumentation). If i					
							ting closure. If th					
							215', per Chevro					
Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Yates Petroleum requests closure based off all work being completed as per the NMOCD/NMSLO approved work plan. Contaminated soils were taken to R360 Environmental Solutions on Highway 62/180.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
							and perform corre					
							narked as "Final F					
							ion that pose a thi					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
OIL CONSERVATION DIVISION												
	$\alpha$			OIL CONDERVITION DIVIDION								
Signature: Chuber Griffin						A Jou						
				Approved by Environmental Specialist:								
Printed Nam	e: Amber (	Griffin										
Title: Envir	onmental D	egulatory Age		Approval Date: 05/09/2016 Expiration Date: ///								
Title. Elivii	omnemai K	Squidiory Age		Approval Date: Expiration Date:					**************************************			
E-mail Address: agriffin@yatespetroleum.com						Conditions of Approval:				Amalad D		
										Attached	-	
Date: May 6, 2016 Phone: 575-748-4111 1RP-										ŀ		

<sup>\*</sup> Attach Additional Sheets If Necessary