

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
900 Rio Brazos Road, Aztec, NM 87410
District IV
220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:19 am, May 18, 2016

Submit to appropriate District Office in accordance with 19-15-29 NMAC

APPROVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: EATA FAJITA STATE #001H	Facility Type: Battery

Surface Owner:	Mineral Owner: State	API No. 30-025-40582
----------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 8	Township 24S	Range 33E	Feet from the 190'	North/South Line South	Feet from the 660'	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.2254906 Longitude -103.6007538

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 40 bbls Oil ; 5 bbls PW	Volume Recovered: 35 bbls Oil ; 4 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 3/6/2016 3:00 pm	Date and Hour of Discovery: 3/6/2016 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes - NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: Mon 3/7/2016 3:27 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a gasket failed. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. This release was contained within the lined facility. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>Jaime Keyes</i>	
Title: Senior Environmental Coordinator	Approval Date: 05/18/2016	Expiration Date: ////
E-mail Address: rgrubbs@concho.com	Conditions of Approval: ///	Attached <input type="checkbox"/>
Date: 05-17-2016 Phone: 432-683-7443		1RP 4216

* Attach Additional Sheets If Necessary