

**APPROVED**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-685-4304
Facility Name:	BOBWHITE 12 STATE COM #003H	Facility Type:	Tank Battery
Surface Owner:	Mineral Owner: State	API No.	30-025-41137

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	12	21S	33E	160	North	496	East	Lea

Latitude 32.5000954

Longitude 103.5190353

#### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 400 bbls Oil	Volume Recovered: 395 bbls Oil
Source of Release: Circulating line	Date and Hour of Occurrence: 3/30/2016 11:00 am	Date and Hour of Discovery: 3/30/2016 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jaime Keyes - NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: Thu 3/31/2016 6:18 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a corroded nipple on a circulating line that ran to an oil tank. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within the lined facility. Concho will have the spill evaluated for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 05/20/2016	Expiration Date: ///	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: ///		Attached <input type="checkbox"/>
Date: 05-19-2016 Phone: 432-685-4304			IRP 4247

\* Attach Additional Sheets If Necessary