

# Atha SWD – Release Notification 04/26/2016 – 1RP-4279

## Photo Log

After Clean-up



Pic 1. South west view of the tank battery.  
Pump area

After Clean-up



Pic 2. Fiber glass flowline repaired

After Clean-up



Pic 3. South east view of the fiber glass flowline  
and release area