

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:44 am, May 24, 2016

Form C-141

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in

accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Prize 27 Federal #2 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-025-31902
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E					Lea County, NM

Latitude N 32.35700° Longitude W 103.65605°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5 bbls oil, 25 bbls produced water	Volume Recovered	25 bbls
Source of Release	Power failure and faulty check valve cause tank overflow	Date and Hour of Occurrence	05/17/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes-NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis	Date and Hour	05/17/2016 @ 11:02 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Power failure and a faulty check valve caused the tank to overflow spilling 5 bbls of oil and 25 bbls of produced water. A vacuum truck recovered 25 bbls of fluids and the power was restored.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 115' x 75' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Casey Summers	Approved by Environmental Specialist: <i>Jam Keyes</i>		
Title: NM Environmental Advisor	Approval Date: 05/24/2016	Expiration Date: 07/24/2016	
E-mail Address: Casey.Summers@oxy.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/approval.		Attached <input type="checkbox"/> IRP 4289
Date: 5-23-16	Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary

nJXK1614531308
pJXK1614531419