

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:29 am, Jul 05, 2016 C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources, Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	432-425-2023
Facility Name	EOG Water Gathering Junction	Facility Type	Water gather junction
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-41067

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	25	26S	33E	2310'	N	990'	W	Lea

Latitude 32.0152 Longitude -103.5309

NATURE OF RELEASE

Type of Release	Open Valve	Volume of Release	350bbbls	Volume Recovered	250bbbls
Source of Release	Oil tank bottom rotted out	Date and Hour of Occurrence	6-28-16	Date and Hour of Discovery	0700
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA			
By Whom?	NA	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*

Lease Operator found valve at water gathering junction open and releasing produced water. Vac truck removed all standing fluid. Consultant will delineate the vertical and horizontal depths of the release and submit a work plan for cleanup. Cleanup method will be based on test results to see if land farm or dig and haul is necessary.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Zane Kurtz		Approved by Environmental Specialist: 	
Title: Sr. Environmental Rep., EOG Resources, Inc.		Approval Date: 07/05/2016	Expiration Date: 09/05/2016
E-mail Address: zane_kurtz@eogresources.com		Conditions of Approval:	
Date: 6-29-2016 Phone: 432-425-2023		Attached <input type="checkbox"/> IRP 4330	

Discrete samples only. Delineate and remediate per
NMOCD guidelines. Ensure BLM concurrence/
approval.

nJXK1618730416
pJXK1618730512

* Attach Additional Sheets If Necessary