

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:04 am, Jul 08, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Enterprise Crude Oil	Contact	Christopher A Spore, P.G.
Address	4600 E Hwy 80, Midland, Tx, 79706	Telephone No.	432-214-3264
Facility Name	Devon Thistle Fed 52H	Facility Type	Central Tank Battery
Surface Owner BLM	Mineral Owner	API No. 30-025-41897	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	28	23S	33E	180	North	1795	West	Lea

Latitude 32.28248 Longitude -103.57966

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	97 bbl	Volume Recovered	20 bbl
Source of Release	Crude Oil transport tank trailer	Date and Hour of Occurrence	7/6/16 0430	Date and Hour of Discovery	7/6/16 0430
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Messages were left with NMOCD District 1 office. Spoke with Carl Chavez in Santa Fe @ 1325 on 7/6/16 and advised of activities. BLM.			
By Whom?	Christopher A Spore, P.G. Enterprise Crude Oil	Date and Hour NMOCD 7/6/16 at 0832 & 0835; BLM 7/6/16 at 0938.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Crude transport driver overfilled tank trailer during loading.
2x vacuum trucks were immediately dispatched to location, and all free oil was recovered.
Emergency line locate was initiated in preparation for excavating impacted caliche.

Describe Area Affected and Cleanup Action Taken.*

Spill site is a caliche tank battery pad. Irregular flow path measuring ~175' x 95'.
Environmental contractor (Talon/LPE) is excavating the flow path of the release and stockpiling the material on plastic.
Impacted caliche/soils will be transported to Lea Land, LLC for disposal.
Confirmation samples will be collected from the excavation to demonstrate remedial action levels have been achieved.
Closure report will be generated and submitted to all involved parties.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Christopher A Spore, P.G.	Approved by Environmental Specialist: 		
Title: Senior Field Environmental Scientist	Approval Date: 07/08/2016	Expiration Date: 09/08/2016	
E-mail Address: caspore@eprod.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> IRP 4338
Date: 7/6/16	Phone: 432-214-3264		

* Attach Additional Sheets If Necessary

nJXK1619028625
pJXK1619028716









devon

THISTLE FED 52H

30-025-41897 NMNM-94186

SL: SEC.28-T23S-R33E 180'FNL & 1795'FWL

BL: SEC.28-T23S-R33E 330'FSL & 1980'FWL

LEA COUNTY, NEW MEXICO

LAT. N 32° 16' 56.851" LONG. W 103° 34' 48.017"

DEVON CORPORATE CONTACT: 800-361-3377

devon
1-800-361-3377
LAT. N 32.28247
LONG. -103.57998