<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mex

**RECEIVED** Energy Minerals and Natura By JKeyes at 9:29 am, Jul 08, 2016

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## **Release Notification and Corrective Action**

Name of Company   Plains Marketing, LP   Contact   Camille Bryant							<b>OPERA</b>	TOR .						
Surface Owner New Mexico State Land   Mineral Owner   Lease No.	Name of Company Plains Marketing, LP													
Surface Owner New Mexico State Land Office  LOCATION OF RELEASE  Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County   Lea  Latitude N 32.73422° Longitude W 103.35255°  NATURE OF RELEASE  Type of Release   Crude Oil   Volume representation of Occurrence   Or/03/2016 @ 08:42   Or/03/2016 @ 08:42    Was Immediate Notice Given?   Yes   No   Not Required   If YES, To Whom?   Verbal notification to Jamie Keyes    By Whom? Camille Bryant   Date and Hour of 70/30/2016 @ 15:11    Was a Watercourse Reached?   Yes   No   If YES, Volume Impacting the Watercourse.    If YES, Volume Impacting the Watercourse   If YES, Volume Impacting the Watercourse   If YES, Volume Impacting the Watercourse was Impacted, Describe Fully.*  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation still operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as 'Final Report' does not releve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not releive the operator of responsibility compliance with any other decral, safe, ye local laws and/or regulations.  OIL CONSERVATION DIVISION  Date: The Population of Approval:   Attached   Discrete samples only. Delineate and remediate per   18P 440														
Continue	Facility Name Lovington Station Tank 116901 Facility Type Tank													
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County   Lea	<b>↓</b>									Lease No.				
Latitude N 32.73422° Longitude W 103.35255°  NATURE OF RELEASE  Type of Release Crude Oil Volume of Release 17 bbls Volume Recovered 15 bbls  Source of Release Tank Date and Hour of Occurrence 07/03/2016 @ 08.42 07/03/2016 @ 08.42  Was Immediate Notice Given? See No Not Required 17 FyES. To Whom Provided the Notice Given? Verbal notification to Jamie Keyes  By Whom? Camille Bryant Date and Hour 07/03/2016 @ 15:11  Was a Watercourse Reached? If YES. Volume Impacting the Watercourse.  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat pose a threat pose a which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, Safe, or local laws and/ar regulations.  OIL CONSERVATION DIVISION  Signature Approved by District Supervisor:  Approved by District Supervisor:  Approved by District Supervisor:  Approved by District Supervisor:  Altached Date:  Attached Date:		LOCATION OF RELEASE												
Latitude N 32.73422° Longitude W 103.35255°   NATURE OF RELEASE		l .												
Type of Release														
Type of Release														
Source of Release Tank    Date and Hour of Occurrence   Date and Hour of Discovery   O7/03/2016 @ 08:42									Volume Recovered 15 bbls					
Was Immediate Notice Given?    Yes   No   Not Required   Verbal notification to Jamie Keyes							Date and Hour of Occurrence			Date and Hour of Discovery				
By Whom? Camille Bryant  Was a Watercourse Reached?  Yes No  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  Approved by District Supervisor:  O7/08/2016  Expiration Date:  Attached Date:  Date:  Discrete samples only. Delineate and remediate per IRP 4340										07/03/2016 @ 08:42				
Was a Watercourse Reached?  Yes ⋈o  If YES, Volume Impacting the Watercourse.  Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  Discrete samples only. Delineate and remediate per  Attached □  1RP 4340														
Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  Discrete samples only. Delineate and remediate per  Attached	By Whom? Camille Bryant						Date and Hour 07/03/2016 @ 15:11							
Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, safe, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  Approval Date:  O7/08/2016  Expiration Date:  Date: The Address: cjbryant@paalp.com  Date: The Address: cjbryant@paalp.com  Discrete samples only. Delineate and remediate per 1RP 4340	Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of crude oil.  Describe Area Affected and Cleanup Action Taken. The released crude oil impacted approximately 1,200 square feet inside the secondary containment of the facility. The release will be remediated as per applicable NMOCD guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD make as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  O7/08/2016  Approval Date:  Discrete samples only. Delineate and remediate per lare 4340  Attached  TITP 4340	∐ Yes ⊠ No													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, sate, or local laws and/or regulations.    OIL CONSERVATION DIVISION	Describe Cause of Problem and Remedial Action Taken.* Internal corrosion caused a hole to develop in the floor of tank 116901 resulting in a release of													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  OIL CONSERVATION DIVISION  Signature  Printed Name: Camille Bryant  Approved by District Supervisor:  O7/08/2016  Expiration Date:  E-mail Address: cjbryant@paalp.com  Date: Phone: (575) 441-1099  Discrete samples only. Delineate and remediate per  1RP 4340														
Approved by District Supervisor:    Approved by District Supervisor:   District Supervisor:	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
Printed Name: Camille Bryant  Approved by District Supervisor:    Date:   Date:   Discrete samples only. Delineate and remediate per   1RP 4340   1RP 4340   1 Phone: (575) 441-1099   1 Phone: (575) 44	Rel						OIL CONSERVATION DIVISION							
Title: Remediation Coordinator  E-mail Address: cjbryant@paalp.com  Date: 15 20   Phone: (575) 441-1099  Date: 15 20   Phone: (575) 441-1099  Discrete samples only. Delineate and remediate per 1RP 4340							Approved by District Supervisor:							
Date: 15 20 6 Phone: (575) 441-1099 Discrete samples only. Delineate and remediate per 1RP 4340	Title: Remediation Coordinator						Approval Da	07/08/201	6	Expiration	09/0 Date:	8/2016		
To detail to the distribution to the safe 14 Blancasses.	Date: 15 2016 Phone: (575) 441-1099						Discrete sam	Oiscrete samples only. Delineate and remediate per 1RP 4340						

nJXK1619033991 pJXK1619034092