

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: DECKARD FEDERAL COM #002H	Facility Type: Battery	
Surface Owner: Fee	Mineral Owner: Federal	API No. 30-025-41382

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	13	24S	33E	190'	North	1980'	West	Lea

Latitude 32.2243538 Longitude -103.5281677

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 5 bbls Oil ; 4 bbls PW	Volume Recovered: 4 bbls Oil ; 4 bbls PW
Source of Release: Corroded butterfly valve	Date and Hour of Occurrence: 6/18/2016 unknown	Date and Hour of Discovery: 6/18/2016 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a corroded butterfly valve on a water leg. A vacuum truck was dispatched to recover all standing fluid and gravel was excavated from the containment before being pressure washed.		
Describe Area Affected and Cleanup Action Taken.* This spill was contained inside the lined containment. Impacted gravel was removed, the facility was cleaned and put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>Janet Hager</i>	
Title: Senior Environmental Coordinator	Approval Date: 07/14/2016	Expiration Date: ///
E-mail Address: atrujillo@concho.com	Conditions of Approval: ///	Attached <input type="checkbox"/>
Date: July 11, 2016 Phone: 575-748-6940		1RP 4332

* Attach Additional Sheets If Necessary