

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:04 am, Aug 05, 2016

Form C-141
August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	(575) 397-8251
Facility Name	State A&B Battery	Facility Type	Battery
Surface Owner	State	Mineral Owner	
		API No.	30-025-23330

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
NE ¼	32	18S	38E					Lea County, NM

Latitude N 32.70557° Longitude W 103.16575°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	25 bbls oil, 40 bbls produced water	Volume Recovered	24 bbls oil, 30 bbls produced water
Source of Release	Tank Overflow caused by human error	Date and Hour of Occurrence	08/01/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes-NMOCD		
By Whom?	Tony Aguilar - Oxy	Date and Hour	08/01/2016 @ 10:59 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A tank overflow caused by human error spilled 25 bbls of oil and 40 bbls of produced water. A vacuum truck recovered 24 bbls of oil and 30 bbls of produced water and the valve was closed.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 100' x 50' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Aguilar		Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 08/05/2016	Expiration Date: 10/05/2016	
E-mail Address: Raymond_aguilar@oxy.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> IRP 4389
Date: 8-4-16	Phone: (575) 397-8251		

* Attach Additional Sheets If Necessary

nJXK1621836104
pJXK1621836199