

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 3:22 pm, Aug 16, 2016

Form C-141  
Revised August 8, 2011

accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	XTO Energy, Inc.	Contact	John Robinson
Address	500 W Illinois, Midland, TX 79701	Telephone No.	575-441-5199
Facility Name	SDE 31 Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	31	23 S	32 E	1980	North	1980	West	Lea



Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release	Produced Water and Oil	Volume of Release	86.86 bbls Water .01 bbls Oil	Volume Recovered	85 bbls water
Source of Release	Suction hose on injection pump	Date and Hour of Occurrence	8-8-16 2:00am	Date and Hour of Discovery	8-8-16 2:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Shelly Tucker BLM Jamie Keyes OCD		
By Whom?	Bo Jackson	Date and Hour	8-8-16 11:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Hose on suction side of injection pump had a hole rubbed in it from laying on the ground. Had a vacuum truck clean up all fluid possible.					
Describe Area Affected and Cleanup Action Taken.* Spill was contained inside berm area around injection pumps. Will clean up contaminated soil and replace with clean soil.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: John Robinson	Approval Date: 08/16/2016	Expiration Date: 10/16/2016
Title: Maintenance Foreman	Conditions of Approval:	
E-mail Address: john_robinson@xtoenergy.com	Attached <input type="checkbox"/>	
Date: 8-10-16 Phone: 575-441-5199	1RP 4398	

Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.

nJXK1622955163  
pJXK1622955241

\* Attach Additional Sheets If Necessary