

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:14 pm, Aug 24, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company El Paso Natural Gas Company, LLC (a Kinder Morgan owned company)	Contact Sheila Castellano	
Address	Telephone No. (719) 520-3719	
Facility Name El Paso Natural Gas Company Line 3031	Facility Type 8-inch Natural Gas Pipeline	
Surface Owner CCBAWH, LLC	Mineral Owner	API No.

LOCATION OF RELEASE – RUPTURE #8

Unit Letter	Section W/2 Sec8	Township 14S	Range 38E	Feet from the 900	North/South Line South	Feet from the 990	East/West Line West	County Lea County, NM
-------------	------------------	--------------	-----------	-------------------	------------------------	-------------------	---------------------	-----------------------

Latitude 33.114214 Longitude -103.124605

NATURE OF RELEASE

Type of Release Inadvertent release of hydrostatic test water	Volume of Release approximately 2000 gallons	Volume Recovered none
Source of Release 8-inch natural gas pipeline	Date and Hour of Occurrence 8/11/16 8:40a MDT	Date and Hour of Discovery 8/11/16 8:40a MDT
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Santa Fe Office: Jim Griswold (505) 476-3465 NMOCD Santa Fe Office: Tomas Oberding (505) 476-3403 NMOCD District 1 Office: Maxey Brown (575) 393-6161 x102	
By Whom? Sheila Castellano	Date and Hour 8/11/16 11:15a MDT	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

EPNG was conducting a hydrostatic spike test of the existing L3031 and the pipeline failed during the test. Test was stopped. Water and soil samples were collected for analysis using Test 8260B.

Describe Area Affected and Cleanup Action Taken.*

Test water release flowed to the west, approximately 10-feet beyond EPNG's existing right of way boundary. Water also flowed approximately 45-feet south along the existing easement and to the north for approximately 248-feet.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Sheila F. Castellano	Approved by Environmental Specialist: 	
Title: Consultant/Contractor	Approval Date: 08/24/2016	Expiration Date: 10/24/2016
E-mail Address: sheila.castellano@kindermorgan.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> 1RP 4416
Date: August 24, 2016	Phone: (719) 520-3719	

nJXK1623754744
pJXK1623754828