

RECEIVED**By JKeyes at 7:34 am, Aug 31, 2016**

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Bone Springs Central Water Flood Facility	Facility Type: Water Flood Injection Facility

Surface Owner: BLM	Mineral Owner: BLM	API No.
--------------------	--------------------	---------

LOCATION OF RELEASE

Unit Letter N	Section 23	Township 18S	Range 32E	Feet from the 660'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.7275472 Longitude -103.7389861

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: estimated 66 bbls	Volume Recovered: 66 bbls
Source of Release: Fiberglass water tank	Date and Hour of Occurrence 8-24-16	Date and Hour of Discovery 8-24-16 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes (NMOCD) Shelly Tucker (BLM) Via Email	
By Whom? Zack Thomas	Date and Hour	8-25-15 7:00 am
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The water flood facility was struck by lightning. Upon being struck, three fiberglass water tanks caught fire. Maljamar VFD was contacted to extinguish the fire. All released fluid was contained within secondary containment.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Northeast side of tanks inside secondary containment. All free standing fluid within secondary containment was recovered with a vacuum truck. Damaged equipment was removed and is scheduled to be replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 08/31/2016	Expiration Date: 10/31/2016
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/	
Date: 8-25-16 Phone: 575-602-2188	Attached <input type="checkbox"/> 1RP 4425	

* Attach Additional Sheets If Necessary

approval.

nJXK1624427112

pJXK1624427211