

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 7:25 am, Sep 14, 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Shell State #3 CTB	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-025-33246

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	36	22S	32E					Lea County, NM

Latitude N 32.34979° Longitude W 103.62951°

### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	10 bbls oil, 10 bbls produced water	Volume Recovered	18 bbls
Source of Release	Power loss caused the tank to spill over	Date and Hour of Occurrence	08/31/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes, Kristen Lynch- NMOCD		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/31/2016 @ 4:16 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A loss of power caused a tank to spill over and leak 10 bbls of oil and 10 bbls of produced water. A vacuum truck recovered all the free-standing fluids and the power was restored.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 250' x 25' both on and off location. Remediation will be completed in accordance with an approved remediation plan from NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name:	Casey Summers	Approved by Environmental Specialist:	<i>Jamie Keyes</i>
Title:	NM Environmental Advisor	Approval Date:	09/14/2016
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	11/14/2016
Date:	9-12-16	Conditions of Approval:	Discrete samples only. Delineate and remediate per NMOCD guidelines.
Phone:	(575) 513-8289	Attached	<input type="checkbox"/> IRP 4440

\* Attach Additional Sheets If Necessary

nJXK1625826606  
pJXK1625826691