

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 8:54 am, Sep 20, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	AIRSTRIP FEE COM #001H	Facility Type:	Flowline

Surface Owner:	State	Mineral Owner:	API No.	30-025-41152
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	07	19S	32E	190'	South	460'	East	Lea

Latitude 32.6684113 Longitude 103.4896698

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100bbls	Volume Recovered: 0bbls
Source of Release: 4" Polyline	Date and Hour of Occurrence: 09-11-2016 10:00 am	Date and Hour of Discovery: 09-11-2016 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes – NMOCD / Amber Groves - SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: Mon 9/12/2016 11:29 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a 4" polyline. The bad section was cut out and replaced.

Describe Area Affected and Cleanup Action Taken.*

This release occurred on a 4" polyline in the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION			
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: 			
Title:	Senior Environmental Coordinator	Approval Date:	9/20/2016	Expiration Date:	11/20/2016
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/> IRP-4444	
Date:	August 19, 2016	Phone:		432-683-7443	

* Attach Additional Sheets If Necessary

Discrete Samples Only
Notify NMOCD of
Sampling for witnessing.
Remediation Plan due
by 10/20/2016.

nKL1626431517
pKL1626431845