

**RECEIVED**

By Kristen Lynch at 3:06 pm, Sep 21, 2016

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP	Contact Jon Bebbington
Address 10 Desta Drive, Suite 400 West	Telephone No. 432-620-4207; 432-413-3601
Facility Name 12200 Gas Gathering Pipeline	Facility Type Natural Gas Gathering Pipeline
Surface Owner BLM	Mineral Owner
API No.	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	3	18S	32E					LEA

**Latitude** N32.782018 **Longitude** W-103.755822

### NATURE OF RELEASE

Type of Release: Raw Natural Gas, Condensate	Volume of Release 6 bbl	Volume Recovered 0 bbl
Source of Release 12200 Gas Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 9-16-2016 14:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N / A		
Describe Cause of Problem and Remedial Action Taken.*  DCP's 12 inch steel 12200 gas gathering line ruptured, releasing an unknown amount of raw natural gas and an estimated 6 bbls of condensate.		
Describe Area Affected and Cleanup Action Taken.*  DCP will excavate and repair the damaged sections and the excavations left open until remedial action can occur. A cleanup plan will be submitted for BLM and OCD Approval.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

### OIL CONSERVATION DIVISION

Signature: <i>Jon D. Bebbington</i>	Approved by Environmental Specialist: <i>Kristen Lynch</i>	
Printed Name: Jon D. Bebbington		
Title: Princ. Environmental Engineer	Approval Date: <b>9/21/2016</b>	Expiration Date: <b>11/21/2016</b>
E-mail Address: jdbbebbington@dcpmidstream.com	<b>NMOCD accepts discrete samples only</b> Conditions of Approval: Notify prior to all sampling events. Submit Remediation Plan no later than 10/21/2016.	
Date: 9-19-2016 Phone: 432-620-4207	Attached <input type="checkbox"/> <b>1RP 4448</b>	

\* Attach Additional Sheets If Necessary

nKL1626554017  
pKL1626554256