

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**REVIEWED**

By Kristen Lynch at 2:06 pm, Oct 20, 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

x ☐ Initial Report ☐ Final Report

Name of Company Matador Resources Company	Contact Catherine Green	
Address 500 N Main St Ste One Roswell NM 88201	Telephone No. 575-623-6601	
Facility Name Young Deep Unit 23	Facility Type Oil	
Surface Owner	Mineral Owner Federal	API No. 30-025-29896

### LOCATION OF RELEASE

Unit Letter J	Section 18S	Township 09	Range 32E	Feet from the 2310	North/South Line S	Feet from the 1980	East/West Line E	County Lea
------------------	----------------	----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	---------------

Latitude 32.761017 Longitude -103.7693566

### NATURE OF RELEASE

Type of Release Oil	Volume of Release ~10BBLs	Volume Recovered ~7BBLs
Source of Release Equalizer on tank not open	Date and Hour of Occurrence	Date and Hour of Discovery 9-29-16, 8am
Was Immediate Notice Given? X <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jason Thibodeaux	
By Whom? Michael Morris	Date and Hour Sep. 29, 2016 8am	
Was a Watercourse Reached? <input type="checkbox"/> Yes x <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Equalizer line was shut. Oil could not flow to next production tank,

Describe Area Affected and Cleanup Action Taken.\*  
~10 BBLs of oil spilled into containment. ~7 BBLs recovered.  
Soil in containment will be removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: Catherine Green

Printed Name: Catherine Green

Approved by Environmental Specialist:

*Kristen Lynch*

Title: Regulatory Analyst

Approval Date: 10/20/2016

Expiration Date: 12/20/2016

E-mail Address: cgreen@matadorresources.com

NMOCD Requires sampling to take place

Conditions of Approval:

NMOCD accepts discrete samples only

Please submit remediation plan no later than

Attached ☐

IRP 4474

Date: Oct. 10, 2016

Phone: 575-623-6601

11/20/2016.

\* Attach Additional Sheets If Necessary

nKL1629450522

pKL1629450685