

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	PATTERSON B 52 FEDERAL COM #002H	Facility Type:	Tank Battery

Surface Owner:	Federal	Mineral Owner:		API No.	30-025-40773
----------------	---------	----------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	05	19S	32E	330	North	330	East	Lea

Latitude 32.6958351 Longitude 103.7809525

NATURE OF RELEASE

Type of Release:	Oil	Volume of Release:	22 bbls Oil	Volume Recovered:	21 bbls Oil
Source of Release:	Tank connection to circulating line	Date and Hour of Occurrence:	November 6, 2016 Unknown	Date and Hour of Discovery:	November 6, 2016 9:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?					
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour:			
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:21 pm, Feb 28, 2017

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a corroded connection from the circulating pump to the tank. The corroded connection was removed and replaced. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist:	<i>[Signature]</i>
Title: Senior HSE Coordinator	Approval Date: 2/28/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/6/17 Phone: 432-683-7443	Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary