

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips	Contact Wendy Acosta Quintero	
Address 29 Vacuum Complex Lane	Telephone No. 432-688-9162	
Facility Name Wyatt #13	Facility Type Well	
Surface Owner BLM	Mineral Owner NMOCD	API No. 30-025-01363

LOCATION OF RELEASE

Unit Letter E	Section 33	Township 17S	Range 33E	Feet from the 1980	North/South Line North	Feet from the 660	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude **32.7928604322935** Longitude **-103.674562565072** NAD83

NATURE OF RELEASE

Type of Release Spill	Volume of Release 16.1 bbl	Volume Recovered 15 bbl
Source of Release Stuffing Box	Date and Hour of Occurrence 12/14/14 2:25 pm	Date and Hour of Discovery 12/14/14 2:25 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom?	Date and Hour 12/16/14 7:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 4:13 pm, Jun 01, 2017

Describe Cause of Problem and Remedial Action Taken.*

On Sunday, December 14th, 2014 @ 1425 Hrs. MST, A discharge occurred at the Wyatt #13. MSO found a leak originating from a stuffing box. The leak resulted in 8.05 BO and 8.05 BPW being released. MSO immediately shut in well. Supervisor and HSE lead were notified. Affected area was 44 foot x 26 foot x 1 inch deep with 8 BO and 7 BPW were recovered. The affected area will be remediated according to NMOCD and COPC guidelines, this is not a PSE.

Describe Area Affected and Cleanup Action Taken.*

The leak resulted in 8.05 BO and 8.05 BPW being released. MSO immediately shut in well. Supervisor and HSE lead were notified. Affected area was 44 foot x 26 foot x 1 inch deep with 8 BO and 7 BPW were recovered. The affected area will be remediated according to NMOCD and COPC guidelines, this is not a PSE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Wendy Acosta Quintero</i>	OIL CONSERVATION DIVISION		
Printed Name: Wendy Acosta Quintero	Approved by Environmental Specialist: <i>[Signature]</i>		
Title: Environmental Coordinator	Approval Date: 6/1/2017	Expiration Date: xx/xx/xxxx	
E-mail Address: wendy.acostaquintero@cop.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 6/1/2017	Phone: 432-688-9162		

* Attach Additional Sheets If Necessary

1RP-3461