From: Yu, Olivia, EMNRD

To: "Troy Hays": Billings, Bradford, EMNRD
Cc: David Sweeney: Mike & Susan Pilcher
Subject: RE: revised C-141 for Cameron Oil
Date: Friday, August 11, 2017 9:59:00 AM

Attachments: 1RP4784.pdf

Dear Mr. Sweeney:

Although NMOCD still disagrees with the assessment of the release volume, the provided information is appreciated.

The 1RP for this incident is

					30-025-		
4784	8/11/2017	А	Cameron	Langlie Mattrix 4 Fed 1	32743	23S-37E-4L	7/20/2017

Please note that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia

----Original Message-----

From: Troy Hays [mailto:Troy@troyhays.net]
Sent: Wednesday, August 9, 2017 10:42 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>

Cc: David Sweeney <dsweeney@cameronoil.com>; Mike & Susan Pilcher <vistaservices@windstream.net>

Subject: Re: revised C-141 for Cameron Oil

Olivia,

Please see the two attachments, this is our documentation for our defense of the C-141 that you have found unacceptable. If you have any questions or comments please feel free to contact myself at 575-420-1108 or 575-627-3284.

Thanks,

David Sweeney

From: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>

Sent: Friday, August 4, 2017 1:56 PM

To: Troy Hays

Cc: Billings, Bradford, EMNRD

Subject: revised C-141 for Cameron Oil

Dear Mr. Hays:

NMOCD will not accept the volume of release reported on the initial C141. Based on photo documentation and NMOCD inspector evaluation, the release is larger than 11 bbls. Photos demonstrate that the release impacted the lease road and was not contained within the firewall, which does not appear to be intact.

If in disagreement, please submit rationale calculations for determination. An amended initial C141 form is due on August 10, 2017.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113 OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

----Original Message-----

From: Troy Hays [mailto:Troy@troyhays.net]
Sent: Wednesday, August 2, 2017 11:32 AM
To: Yu, Olivia, EMNRD < Olivia.Yu@state.nm.us>

Subject: revised C-141 for Cameron Oil

Attached is the revised C-141 for Cameron Oil & Gas, Inc.

Troy Hays, LLC CPA Post Office Box 1456 Roswell, NM 88202-1456 Phone (575) 622-5544 Fax (575) 623-3521 District !
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

			Rele	ease Notific	catio	n and Co	orrective A	etion	ا \	Denied			
						OPERA'	ГOR		Initia	al Report	_ [Final Report	
Name of Company Cameron Oil & Gas, Inc.						Contact David Sweeney							
Address PO Box 1455 Roswell, NM 88202-1455						Telephone No. 575-420-1108 575-627-3284							
Facility Na	me Langl	ie Mattix 4 I	Federal 1			Facility Typ	e Tank Battery	/					
Surface Owner Mineral Owner)wner	er API No. 30-025-32743							
				LOCA	TIO	N OF RE	LEASE						
Unit Letter L	Section 4	Township 235	Range 37E	Feet from the 1650	1	orth/South Line Feet from the East/West Line County South 660 West Lea							
			Latitud	le	L	Longitude NAD83							
				NAT	'URE	OF REL	EASE						
Type of Rele	Type of Release Oil & Water						Volume of Release 11 BBLS Volume Recovered 0						
Source of Re							Iour of Occurrence	e	Date and	Hour of Dis	covery		
Was Immedi	ate Notice (Yes [] No 🔽 Not Re	equired	If YES, To	Whom?						
By Whom?	By Whom?						Date and Hour 7/20/17						
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
If a Watercou	If a Watercourse was Impacted, Describe Fully.*					RECEIVED							
								1.51	nm A	ua 04	201	7	
						By Oil	ivia Yu at	1.54	piii, A	ug 04,	201		
Describe Cau replaced.	ise of Probl	em and Reme	dial Actio	n Taken.* On 7/20	0/17 a h	ole in the flov	vline between the	wellhea	d and heate	er treater. Ti	ne flowl	ine was	
термеси.													
				en.* 11 BBLS o 3 BBLS of fluid,									
around nearer	i ireaici. A	vacoum muck	presed up	5 BBE5 of flaid,	the area	1 1413 300 34 1	cct. 71 backhoc ci	icarica in	ic aren and	madica 5 ya	103 10 0	andance.	
I hereby certi	fy that the i	nformation gi	ven above	is true and compl	ete to tl	ne best of my	knowledge and u	nderstan	d that purs	uant to NM	OCD ru	les and	
regulations al	l operators	are required to	o report ar	id/or file certain re	elease n	otifications ar	id perform correc	tive action	ons for rele	ases which	may en	danger	
				e of a C-141 repo									
				investigate and re tance of a C-141 r									
federal, state,				Rance of a C-1+1 i	Срои и	ocs not renev	e the operator of t	Саронан	onity for co	mphanee w	illi dily	ottici	
A						OIL CONSERVATION DIVISION							
Signature: C	⇒Ìa	uid_	كالسالا	ener	ļ								
Printed Name: David Sweeney						Approved by Environmental Specialist:							
Title: Operation Manager						Approval Date: Expiration Date:							
E-mail Address: dsweeney@cameronoil.com													
						Conditions of Approval:							
Date:	8/1/17	Phone	:575-420-	1108 575-627-32	284								

^{*} Attach Additional Sheets If Necessary