

From: [Yu, Olivia, EMNRD](#)
To: [Aaron Pachlhofer](#)
Subject: RE: Ling Battery Spill C-141
Date: Thursday, October 12, 2017 7:14:00 AM
Attachments: image001.png

Good morning Mr. Pachlhofer:

Noted. Thanks for the revised C-141, but an annotated one will not be sent back to you.

Thanks,
Olivia

From: Aaron Pachlhofer [mailto:aaronp@forl.com]
Sent: Wednesday, October 11, 2017 4:21 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Subject: RE: Ling Battery Spill C-141

Not sure why I put Ling #2 on there, chalk that up to a typo.

The battery is the Ling Federal (Commingle). It is on the same well pad with our Ling Federal 3 well. Attached is a revised C-141 to reflect the proper battery name. I have also attached a picture of the sign at the battery for your reference.



Aaron Pachlhofer, P.G.
Environmental Coordinator
Fasken Oil and Ranch, Ltd.
6101 Holiday Hill Road
Midland, TX 79707
432-687-1777 Office
830-377-9190 Cell

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]
Sent: Wednesday, October 11, 2017 12:18 PM
To: Aaron Pachlhofer <aaronp@forl.com>; Shelly Tucker <stucker@blm.gov>
Subject: RE: Ling Battery Spill C-141

Dear Mr. Pachlhofer:

Please be advised that the initial notification was for Ling Federal #3 tank battery. Please verify.

The 1RP for this incident is

4842	10/11/2017	A	Fasken Oil	Ling Federal #2 battery		19S-34E-31B	10/11/2017
------	------------	---	------------	-------------------------	--	-------------	------------

Please note that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD

approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Aaron Pachlhofer [<mailto:aaronp@forl.com>]
Sent: Tuesday, October 10, 2017 3:27 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Shelly Tucker <stucker@blm.gov>
Subject: Ling Battery Spill C-141

Olivia and Shelly,

Please find C-141 attached. Please note that we do not have the police report yet, but I will forward it as soon as I have it.

Thanks,



Aaron Pachlhofer, P.G.
Environmental Coordinator
Fasken Oil and Ranch, Ltd.
6101 Holiday Hill Road
Midland, TX 79707
432-687-1777 Office
830-377-9190 Cell

From: Eng Copier
Sent: Tuesday, October 10, 2017 4:21 PM
To: Aaron Pachlhofer
Subject: Attached Image

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Fasken Oil and Ranch, Ltd	Contact: Aaron Pachlhofer	
Address: 6101 Holiday Hill Road, Midland, TX, 79707	Telephone No.: 432-687-1777	
Facility Name: Ling Federal Tank Battery (Comingled)	Facility Type: Tank Battery	
Surface Owner: Larry Hughes	Mineral Owner: BLM	API No.: N/A

LOCATION OF RELEASE

Unit Letter B	Section 31	Township 19S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.622030° Longitude -103.597460°

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release 40	Volume Recovered 31
Source of Release: Tanks	Date and Hour of Occurrence: 10/4/17 unknown time	Date and Hour of Discovery 10/5/17, 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Reported <u>Oliva Yu</u>	
By Whom? Aaron Pachlhofer	Date and Hour: 10/5/17, ~2:30 p.m. CST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*


Spill resulted from vandalism by gunfire.

Describe Area Affected and Cleanup Action Taken.*

Approximately 2,200 ft2 inside of firewall affected. Fully contained.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Aaron Pachlhofer, P.G.	Approval Date:	Expiration Date:
Title: Environmental Coordinator	Conditions of Approval:	
E-mail Address: aaronp@forl.com	Attached <input type="checkbox"/>	
Date: 10/8/17 Phone: 432-687-1777		

* Attach Additional Sheets If Necessary

FASKEN OIL AND RANCH, LTD.

LING FEDERAL LEASE

UNIT B, SEC. 31, T19S, R34E

LEA COUNTY, NEW MEXICO

SURFACE COMMINGLE PERMIT

NO. CTB-598