<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

				50	iiita 1	C, 141VI 075	03				
			Rele	ease Notific	catio	n and Co	rrective A	ction	1		
						<b>OPERATOR</b>			$\  \  \  \  \  \  \  \  \  \  \  \  \  $		
Name of Company: EOR Operating Company						Contact: Jamie Hogue					
Address: 777 N. Eldridge Pkwy, Suite 150 Houston, TX 77079						Telephone No.: 832-485-8522					
Facility Name: Milnesand Unit Battery 3						Facility Type: Oil & Water					
Surface Ow	ner: Vern	on B Rogers	ı	Mineral C	wner:	Various (Mi	lnesand SA Uni	t)	API No		
				LOCA	ATIO	N OF RE	LEASE				
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/	West Line	County	
J	19	8S	35E							Roosevelt	
<b>Latitude</b> : 33.611855 <b>Longitude:</b> 103.402620											
Type of Rele	ase: Oil	INA	UKI	Volume of Release: 37 bbls Volume Recovered: 37 bbls							
Source of Re		htning		Date and Hour of Occurrence: 5/5  Date and Hour of Discovery: 5/5/ 8:00am							
Was Immedi	ate Notice (			If YES, To Whom?							
		No Not Ro	equired	d Jamie L Hogue – VP Regulatory Affairs							
By Whom?	Carlos Bo	erator		Date and Hour: 5/5/15 - 8:00am							
Was a Water	course Read	7 <i>X</i> - No		If YES, Volume Impacting the Watercourse.							
If a Watercon	maa yyaa Im	k			CENTED						
ii a watercot	irse was iiii	pacted, Descr	ibe ruily.	•		KE	CEIVED				
						By (	OCD Distric	t 1 a	t 9:09 al	m, May 06, 2015	
Describe Cau	ise of Probl	em and Reme	dial Action	n Taken.*							
The night of	5/4/15 stori	ns came throu	igh the Mi	lnesand area. Lig						ne of the tanks was destroyed	, and
										collecting production. He	
				then put into hole						total destroyed. The oil that	was
Describe Are	a Affected	and Cleanup A	Action Tak	ken.*			-				
										s able to be vacuumed up wa	
up and flowlin			ick and pu	t into notding tan	k at MS	SO Battery 5 IC	or storage and cle	an up.	Bordayo ro	istabout crew assisted with c	iean
			tanks are	removed, clean uj	p is cor	nplete and nev	tanks are set.				
										uant to NMOCD rules and	
										ases which may endanger eve the operator of liability	
										, surface water, human health	1
										ompliance with any other	
federal, state	, or local la	ws and/or regu	ulations.		1			~===			
	0.			OIL CONSERVATION DIVISION							
Signature:	Jame.	L Hogue									
Printed Name: Jamie L Hogue						Approved by Environmental Specialist:					
Title: VP Regulatory Affairs						Approval Dat	e: 05/06/2015		Expiration	Date: 08/06/2015	
E-mail Addre	ess: ihogue	@enhancedoi	lres.com			Conditions of	Approval:				
E-mail Address: jhogue@enhancedoilres.com						Site samples required. Delineate and				Attached 257420	
Date: 5/5/20				: 832-485-8522			e as per MNOCD				
* Attach Addi	tional She	ets If Necess			Geotag photographs of remediation pKJ1512637338						

required.