

From: [Yu, Olivia, EMNRD](#)
To: [Lowry, Joel](#); MNaranjo@slo.state.nm.us; [Mann, Ryan](#)
Cc: [DeAnn Grant](#); [Rebecca Haskell \(rhaskell@concho.com\)](mailto:rhaskell@concho.com)
Subject: RE: 1RP-4569 - Merlin State Com 002H - Remediation Summary and Closure Report
Date: Friday, March 30, 2018 1:13:00 PM
Attachments: approved_1RP-4569 - Merlin State Com 002H - Remediation Summary and Closure Repor....pdf
approved_1RP-4569 - Merlin State Com 002H - Final C-141.pdf

Dear Ms. Haskell:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4569** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Like approval from NMSLO required.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Lowry, Joel <JLowry@trcsolutions.com>
Sent: Tuesday, March 6, 2018 7:44 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; MNaranjo@slo.state.nm.us
Cc: [DeAnn Grant <agrant@concho.com>](mailto:agrant@concho.com); [Rebecca Haskell \(rhaskell@concho.com\)](mailto:rhaskell@concho.com)
<rhaskell@concho.com>
Subject: 1RP-4569 - Merlin State Com 002H - Remediation Summary and Closure Report

Please find attached a revised draft of the *Remediation Summary and Closure Report* along with a Final C-141 that has been prepared for the Merlin State Com 002H (1RP-4569). The release site is located in Unit Letter "D", Section 32, Township 21 South, Range 34 East in Lea County, New Mexico on land administered by the New Mexico State Land Office. If you have any questions or need any additional information, please feel free to contact Becky Haskell or myself by phone or email.
Thanks.

Respectfully,

Joel Lowry
Senior Project Manager



2771 Highway 214, Denver City, TX 79323
C: 432-466-4450

[LinkedIn](#) | [Twitter](#) | [Blog](#) | www.trcsolutions.com