

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Production LLC (OGRID #217955)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: WINDWARD FEDERAL #002H	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-41408

LOCATION OF RELEASE

Unit Letter C	Section 30	Township 24S	Range 32E	Feet from the 190'	North/South Line North	Feet from the 1750'	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude/Longitude 32.1950645,-103.7173386

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 18 bbls PW
Source of Release: Pump	Date and Hour of Occurrence: 7/31/2016 unknown	Date and Hour of Discovery: 7/31/2016 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 10:24 am, Apr 18, 2018

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a packing lubricator on the pump packing blew out. A Vacuum truck was dispatched to recover all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon Hitchcock</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheldon Hitchcock	Approved by Environmental Specialist: <i>ey</i>	
Title: HSE Coordinator	Approval Date: 4/18/2018	Expiration Date: xx/xx/xxxx
E-mail Address: slhitchcock@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/11/17	Phone: 575-746-2010	

* Attach Additional Sheets If Necessary

1RP-4391