From: Yu, Olivia, EMNRD

To: "Sheldon Hitchcock"; stucker@blm.gov; James Amos@blm.gov
Cc: Rebecca Haskell; Robert McNeill; Dakota Neel; Christopher Gray

Subject: RE: (C-141 Final) Windward Federal #2H (TB) (30-025-41408) 7-31-2016 (1RP-4391)

Date: Wednesday, April 18, 2018 10:30:00 AM

Attachments: approved_(C-141 Final) Windward Federal #2H (TB) (30-025-41408) 7-31-2016 (1RP-4391).pdf

Dear Mr. Hitchcock:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4391** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Sheldon Hitchcock <SLHitchcock@concho.com>

Sent: Monday, December 11, 2017 1:21 PM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>; stucker@blm.gov; James_Amos@blm.gov

Cc: Rebecca Haskell <RHaskell@concho.com>; Robert McNeill <RMcNeill@concho.com>; Dakota

Neel <DNeel2@concho.com>; Christopher Gray <CGray@concho.com>

Subject: (C-141 Final) Windward Federal #2H (TB) (30-025-41408) 7-31-2016 (1RP-4391)

Ms. Yu/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Sheldon L. Hitchcock HSE Coordinator COG Operating LLC 2407 Pecos Avenue | Artesia, NM 88210 Cell: 575-703-6475 | Office: 575-746-2010

slhitchcock@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the

information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.