

From: Kimberly M. Wilson
To: [Jones, Kellie, EMNRD](#)
Cc: [David Adkins](#)
Subject: FW: Fasken Oil and Ranch Denton #10
Date: Tuesday, March 22, 2016 9:50:09 AM
Attachments: image001.png
20110509073216.pdf

Kellie see below regarding the liner. I have also attached a copy of the historic work plan and approval.

Kimberly M. Wilson

Project Manager

Office: 575.616.4023

Cell: 575.602.3826

Fax: 575.746.8905

Emergency: 866.742.0742

Web: www.talonlpe.com



From: David Adkins
Sent: Tuesday, March 22, 2016 9:45 AM
To: Kimberly M. Wilson
Subject: FW: Fasken Oil and Ranch Denton #10

Here's another email from OCD directing liner installation and permission to backfill

David J. Adkins

District Manager Artesia

Office: 575.746.8768

Direct: 575.616.4022

Cell: 575.441.4835

Fax: 575.746.8905

Emergency: 866.742.0742

Web: www.talonlpe.com



From: mstubblefield@talonlpe.com [<mailto:mstubblefield@talonlpe.com>]
Sent: Wednesday, March 16, 2011 12:34 PM
To: David Adkins
Subject: Fw: Fasken Oil and Ranch Denton #10

Sent from my BlackBerry Smartphone provided by Alltel

From: "Leking, Geoffrey R, EMNRD" <GeoffreyR.Leking@state.nm.us>
Date: Wed, 16 Mar 2011 10:26:13 -0500
To: Michael Stubblefield<mstubblefield@talonlpe.com>
Subject: RE: Fasken Oil and Ranch Denton #10

Mike

Per our discussion of this morning, Fasken will drape sufficient liner over the north end of the excavation to prevent recharge from contacting the elevated chlorides at this location. The liner can then be set in the excavation as normally done and backfill may be placed. Thank you for your cooperation in this project.

Geoffrey Leking
Environmental Engineer
NMOCD-Hobbs
1625 N. French Drive
Hobbs, NM 88240
Office: (575) 393-6161 Ext. 113
Cell: (575) 399-2990
email: geoffreyr.leking@state.nm.us

From: Michael Stubblefield [<mailto:mstubblefield@talonlpe.com>]
Sent: Tuesday, March 15, 2011 11:04 AM
To: Leking, Geoffrey R, EMNRD
Subject: Fasken Oil and Ranch Denton #10

Dear Mr. Geoffrey Leking,

I'm forwarding you the analytical results received from Cardinal Laboratories for the soil samples collected at the Denton #10. The soil samples were collected from the side walls of the excavated area on 3/8/2011 and 3/14/2011. After receiving the analytical results from Cardinal Laboratories dated 3/11/2011, additional excavation actions were then taken on the west side wall. There is an active SWD disposal line located near the excavated area on the north side wall. Due to a safety factor and the possibility of creating another release, we are requesting no further excavation to be required on the north side wall at the Denton #10. Fasken Oil and Ranch is requesting approval to proceed with the placement of a 20 Mil. liner into the bottom of the excavated area and to start placing backfill material into the excavated area.

Sincerely,

Mike Stubblefield
Talon/LPE Project Manager

addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.