

Huckeye Rd

Huckeye Rd

APPROVED

By Olivia Yu at 1:48 pm, May 07, 2018

NMOCD grants
backfill approval
to 1RP-4202.


0.5' DEEP
(SURFACE SCRAPE)

Corresponding areas approximately
10 feet north of lease road and
underground pipeline.
Field data has chloride
concentrations ranging from 120 -
440 ppm at 6" depth.

Lease Road not remediated

Red dots represent sample locations with
field data that has chlorides concentrations
ranging from 2.00 - 11.55 ppt at 6" depth.

EXPLANATION	
▲	PRIOR VERTICAL SAMPLE LOCATIONS
○	TETRA TECH SOIL BORING SAMPLE LOCATIONS
---	BURIED PIPELINE
---	OVERHEAD ELECTRIC LINE
---	SURFACE PIPELINE
□	EXCAVATED AREA



ConocoPhillips

Figure 4

EVGSAU Injection Header #4
(32 796871, -103 471310)

Excavation Areas & Depths Map

Lea County, New Mexico

Project : 212C-MD-00937

Date : 10/18/2017

File : H:\GIS\212C-MD-00937

