

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Initial only

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Marathon Oil Company	Contact Raquel Chacon
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 281-910-0441(cell) 575-297-0988 (office)
Facility Name Angell COM #1	Facility Type Oil and gas production facility

Surface Owner: Private	Mineral Owner	API No. 30-025-37902
------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter A	Section 11	Township 17S	Range 36E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.855019 Longitude -103.318259 NAD83

NATURE OF RELEASE

Type of Release: Oil	Volume of Release 11 barrels	Volume Recovered 11 barrels
Source of Release: Tank overflow	Date and Hour of Occurrence 10/5/2017 10:00 pm	Date and Hour of Discovery 10/5/2017 10:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Raquel Chacon	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

RECEIVED
By Olivia Yu at 3:39 pm, Oct 23, 2017

Describe Cause of Problem and Remedial Action Taken.*

Due to Operator Error, no automation on site, operator did not gauge location day before and approximately 11 bbls of oil were spilled and contained in a lined secondary containment. Vacuumed unit called out onsite and recovered 11 bbls.

Describe Area Affected and Cleanup Action Taken.*

Base material (chat) was removed from lined containment. Liner was checked for integrity and intact, new material was brought in to protect plastic liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Raquel Chacon

Title: Sr. HES Environmental Professional

E-mail Address: rchacon@marathonoil.com

Date: October 9, 2017

Phone: 281-910-0441 (cell) 575-297-0988 (office)

Approved by Environmental Specialist:

Approval Date:

10/23/2017

Expiration Date:

Conditions of Approval:

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

Attached ☐

nOY1729656856

* Attach Additional Sheets If Necessary







CRUDE OIL

104-33
104-76