

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised April 3, 2017

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA Inc.	Contact: Josepha DeLeon	
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 575-263-0424	
Facility Name: State D&E Battery	Facility Type: Battery	
Surface Owner N/A <b>State</b>	Mineral Owner N/A <b>State</b>	API No. 30-025-32298; 30-025-21258

### LOCATION OF RELEASE

Unit Letter <b>N</b>	Section 31	Township 17S	Range 35E	Feet from the 330	North/South Line South	Feet from the 695	East/West Line West	County Lea
-------------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

### GPS Coordinates:

D&E Battery - **32.785947, -103.500665.**

State D is 3002532298, 32.7851639 and -103.5032425 NAD 83

State E is 3002521258, 32.5641022 and -103.3829498 NAD 83

### NATURE OF RELEASE

Type of Release: Venting	Volume of Release: estimated at 30 MCF per day <b>Final volume vented 419 MCF</b>	Volume Recovered: 0 MCF
Source of Release: Flare Stack	Date and Hour of Occurrence: <b>Started 04/19/2018; 01:42 PM</b> <b>Ended 05/03/2018; 11:30 PM</b>	Date and Hour of Discovery: 04/19/2018; 01:42 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Josepha DeLeon	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		

**RECEIVED**

**By Olivia Yu at 8:21 am, May 09, 2018**



Describe Cause of Problem and Remedial Action Taken.\*

Venting due to 3<sup>rd</sup> party shut down (DCP line leak). Operations shut in wells and routed gas to minimize emissions and stay in contact with 3<sup>rd</sup> party to restore normal operations as soon as safely and practicable.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 	
Title: HES Specialist – Compliance Support, Environmental	Approval Date: <b>5/9/2018</b>	Expiration Date: <b>xx/xx/xxxx</b>
E-mail Address: jdx@chevron.com	Conditions of Approval:	
Date: May 8, 2018 Phone: 575-263-0424	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**fOY1812930844**

**1RP-5049**

**nOY1812930960**

**pOY1812930788**