

From: [Yu, Olivia, EMNRD](#)
To: [DeLeon, Josepha](#); [Mann, Ryan](#)
Cc: [Bates, Austin D.](#); [Brown, Maxey G, EMNRD](#)
Subject: RE: 20180416 State D&E Battery Flare Initial C-141 Signed.pdf
Date: Wednesday, May 9, 2018 8:59:00 AM
Attachments: image001.png
reviewed_1RP5049_20180416 State DE Battery Flare Initial C-141 Signed.pdf

Dear Ms. DeLeon:

Please remember to include NMSLO in all flare/venting notifications from wells and batteries on State surface or mineral ownerships.

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-5049** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: DeLeon, Josepha <JDxD@chevron.com>
Sent: Tuesday, May 8, 2018 9:13 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Bates, Austin D. <ABates@chevron.com>; Brown, Maxey G, EMNRD <MaxeyG.Brown@state.nm.us>
Subject: RE: 20180416 State D&E Battery Flare Initial C-141 Signed.pdf

Attached is the final C141 for State D&E.

D&E Battery - 32.785947, -103.500665.

Started 04/19/2018; 01:42 PM

Ended 05/03/2018; 11:30 PM
Final volume vented 419 MCF

From: Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]
Sent: Monday, May 07, 2018 8:57 AM
To: DeLeon, Josepha <JDxD@chevron.com>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Bates, Austin D. <ABates@chevron.com>
Subject: **[**EXTERNAL**]** RE: 20180416 State D&E Battery Flare Initial C-141 Signed.pdf

Good morning Ms. DeLeon:

Where is the battery actually situated? Please provide GPS coordinates of the State D and E battery, as the respective wells are more than 10 miles apart. Also, how many days did the flaring occur?

Thanks,
Olivia

From: DeLeon, Josepha <JDxD@chevron.com>
Sent: Thursday, May 3, 2018 10:38 AM
To: Brown, Maxey G, EMNRD <MaxeyG.Brown@state.nm.us>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Bates, Austin D. <ABates@chevron.com>
Subject: 20180416 State D&E Battery Flare Initial C-141 Signed.pdf

Attached is initial C-141 on venting event at State D&E Battery. Final will be submitted once 3rd party restores normal operation.

*Josie DeLeon, HES Specialist -
Compliance Support - Environmental*

**Chevron - MCBU
(New Mexico, East Texas and Ft. Stockton Areas)**

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdxd@chevron.com



