

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC OGRID #229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443
Facility Name: Bobwhite 12 State Com #004H (1RP-4942)	Facility Type: Wellhead

Surface Owner: State	Mineral Owner: State	API No. 30-025-41092
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 12	Township 21S	Range 33E	Feet from the 160	North/South Line North	Feet from the 496	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude_32.5000725__ Longitude_-103.5330048__ NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 145 bbl.	Volume Recovered: 140 bbl.
Source of Release: Packing	Date and Hour of Occurrence: January 15, 2018 4:00 pm	Date and Hour of Discovery: January 15, 2018 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu – NMOCD / Ms. Honea – SLO	
By Whom? Dakota Neel	Date and Hour: January 16, 2018 2:32 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 1:59 pm, Jul 09, 2018

Describe Cause of Problem and Remedial Action Taken.*



The packing on the pumping well over-pressured and ruptured. The well was shut in and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release was on location. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

Remediation activities were conducted in accordance with an NMOCD and NMSLO-approved Workplan and/or associated correspondence with respective regulatory representatives. Please reference the Workplan March 5, 2018 and Remediation Summary and Closure Report dated June 19, 2018 for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
		Approved by Environmental Specialist: 	
Printed Name: Rebecca Haskell			
Title: HSE Coordinator	Approval Date: 7/9/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: rhaskell@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: June 19, 2018 Phone: 432-818-2372			

* Attach Additional Sheets If Necessary-

1RP-4942