

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: MC Federal #014	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-38738
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	21	17S	32E	330	North	2010	East	Lea

Latitude: 32 8264313 Longitude: -103 7694473 NAD83

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30bbbls	Volume Recovered: 29bbbls
Source of Release: Circulating pump line piping	Date and Hour of Occurrence: 11-19-2017 8:00am	Date and Hour of Discovery: 11-19-2017 8:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu / Ms. Tucker	REVISED 3:41 pm, Jul 20, 2018
By Whom? Rebecca Haskell	Date and Hour: 11-19-2017 2:45PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:52 pm, Nov 20, 2017



Describe Cause of Problem and Remedial Action Taken.*

Circulating line piping developed a hole. Isolated pipe with hole and replacing with new piece of piping.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Aaron Lieb	Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator	Approval Date: 11/20/2017	Expiration Date:
E-mail Address: alieb@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/20/2017 Phone: 575-748-1553	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1732453631

1RP-5131

pOY1820156189