

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Pygmy 27 State #001H	Facility Type: Tank Battery	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-40352

LOCATION OF RELEASE

Unit Letter D	Section 27	Township 21S	Range 33E	Feet from the 330	North/South Line North	Feet from the 190	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.4561577 Longitude -103.5683441 NAD83

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 20 bbl. Oil 20 bbl. Produced Water	Volume Recovered: 13 bbl. Oil 12 bbl. Produced Water
Source of Release: Gasket Failure	Date and Hour of Occurrence: July 30, 2018 11:00am	Date and Hour of Discovery: July 30, 2018 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu- NMOCD Christina Hernandez - NMOCD Ryan Mann- SLO	
By Whom? DeAnn Grant	Date and Hour: July 30, 2018 4:46pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 1:27 pm, Aug 02, 2018

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a failed gasket. The gasket is being replaced.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

DeAnn Grant

Printed Name: DeAnn Grant

Approved by Environmental Specialist:

[Signature]

Title: HSE Administrative Assistant

Approval Date: **8/2/2018**

Expiration Date:

E-mail Address: agrant@concho.com

Conditions of Approval:

Attached ☐

Date: July 30, 2018

Phone: 432-253-4513

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

1RP-5143

* Attach Additional Sheets If Necessary

nOY1821448734

pOY1821449586