

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Cullen Rosine</b>	
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-391-3133</b>	
Facility Name: <b>MCA 1C</b>	Facility Type: <b>Flow line</b>	
Surface Owner: Federal	Mineral Owner: N/A	API No. 30-025-23706

### LOCATION OF RELEASE

Unit Letter <b>M</b>	Section 20	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
Latitude <u>32.8131905</u> Longitude <u>-103.7842789 NAD83</u>								

### NATURE OF RELEASE

Type of Release: <b>1.8 BBL Produce Water &amp; 9.2 Oil</b>	Volume of Release: <b>11 BBL</b>	Volume Recovered: 8 BBL
Source of Release: <b>Flow line</b>	Date and Hour of Occurrence <b>11/11/2016 1030hrs</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch	
By Whom? <b>Cullen Rosine</b>	Date and Hour: <b>11/15/16 1235 hrs via email</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		
Describe Cause of Problem and Remedial Action Taken. * On November 11, 2016 at 1030hrs a flow line leak occurred on the MCA 1C header trunk line. Total spill volume was 11 BBL of which 8 BBL were recovered. Spill site will be remediated according to NMOCD and COPC guidelines.		
Describe Area Affected and Cleanup Action Taken. * Area 1: 93ft x 51ft x 2 inches Area 2: 120ft x 15ft x 1 inch		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Cullen Rosine		<b>OIL CONSERVATION DIVISION</b>
Printed Name: Cullen Rosine		
Title: HSE Specialist	Approval Date:	Expiration Date:
E-mail Address: <b>Cullen.j.rosine@cop.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/15/16 Phone: 575-391-3133		

\* Attach Additional Sheets If Necessary

nOY1821258273

1RP-5141

pOY1821258767