Ms. Blaney:

Delineation is not completed for 1RP-4838. Please be advised that NMOCD does not consider an 'impermeable layer' as an acceptable rationale to not complete delineation. A release characterization plan is still required.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Friday, November 3, 2017 1:12 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Raley, Jim <James.Raley@wpxenergy.com>
Subject: WPX/RKI Toro 22-3 incident

Good afternoon, Attached is the characterization and closure summary for the Toro 22-3 incident. Please let me know if you have any questions or concerns. Thank you and have a great weekend,

Karolina Blaney Environmental Specialist WPX Energy Office: (575) 885-7514 Cell: (970) 589-0743 karolina.blaney@wpxenergy.com

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]
Sent: Friday, October 06, 2017 2:50 PM
To: Blaney, Karolina <<u>Karolina.Blaney@wpxenergy.com</u>>
Cc: Raley, Jim <<u>James.Raley@wpxenergy.com</u>>
Subject: [EXTERNAL] RE: WPX/RKI Toro 22-3 - C-141

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

Dear Ms. Blaney:

The 1RP for this incident is

					30-025-	19S-35E-	
4838	10/6/2017	А	WPX/RKI	Toro 22-3	35253	22K	9/21/2017

Please note that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Thursday, October 5, 2017 3:09 PM
To: Yu, Olivia, EMNRD <<u>Olivia.Yu@state.nm.us</u>>
Cc: Raley, Jim <<u>James.Raley@wpxenergy.com</u>>
Subject: RE: WPX/RKI Toro 22-3 - C-141

Good afternoon Ms. Yu,

Attached is the initial C-141 report. Please let me know if you have any questions or suggestions. I will be on PTO starting Monday, 10/9 returning on 10/23. If you need immediate assistance with environmental issues, please contact Jim Raley who's copied on this email.

Thank you and have a great afternoon,

Karolina Blaney

Environmental Specialist WPX Energy Office: (575) 885-7514 Cell: (970) 589-0743 karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Thursday, September 21, 2017 12:23 PM
To: 'Yu, Olivia, EMNRD' <<u>Olivia,Yu@state.nm.us</u>>
Cc: Raley, Jim <<u>james.raley@wpxenergy.com</u>>
Subject: RE: WPX/RKI Toro 22-3 - initial spill notification

Good morning,

WPX had a spill this morning, 9/21/17 at 8:30 am, at the Toro 22-3 well pad; API 30-025-35253. The cause of this spill is equipment failure – corroded produced water tank. Approximately 120 bbls of produced water were spilled inside dirt SPCC containment. 110 bbls were recovered with a vac truck. The impacted surface will be scraped off as soon as the line locates are cleared. The C-141 report will be submitted to you in the next 15 days, however, please do not hesitate to call me if you have any questions or concerns.

Thank you and have a great day,

Karolina Blaney Environmental Specialist WPX Energy Office: (575) 885-7514 Cell: (970) 589-0743 karolina.blaney@wpxenergy.com