

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443	
Facility Name: <b>Pygmy 27 State #001H Battery</b>	Facility Type: Flowline	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-40352

### LOCATION OF RELEASE

Unit Letter L	Section 27	Township 21S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.4471062 Longitude -103.5665927 NAD83

### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 bbl.	Volume Recovered 0 bbl.
Source of Release Flowline Rupture	Date and Hour of Occurrence August 13, 2018 1:00pm	Date and Hour of Discovery August 13, 2018 1:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu - NMOCD Christina Hernandez - NMOCD Ryan Mann - SLO	
By Whom? DeAnn Grant	Date and Hour August 14, 2018 5:25pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

**By Olivia Yu at 11:26 am, Aug 20, 2018**



Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a flowline rupture. The line is being replaced

Describe Area Affected and Cleanup Action Taken.\*

The release occurred in the pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 8/20/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: August 14, 2018	Phone: (432) 253-4513	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

\* Attach Additional Sheets If Necessary

nOY1823241508

pOY1823241684

1RP-5159