

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy (6137)	Contact: Stephen Richards, Devon Completions Foreman	
Address: PO Box 250, Artesia, NM 88211	Telephone No.: 575-252-3717	
Facility Name: Thistle Unit 111H	Facility Type: Oil Well	
Surface Owner: State	Mineral Owner: State	API No. 30-025-44418

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	23S	33E	233	NORTH	630	EAST	LEA

Latitude 32.296956 N Longitude -103.552832 W NAD83

NATURE OF RELEASE

Type of Release: Treated Produced Water	Volume of Release: 14.26 bbls	Volume Recovered: 0 bbls
Source of Release: Frac tanks	Date and Hour of Occurrence: 7/30/18, 12:30 AM	Date and Hour of Discovery: 7/30/18, 12:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A	<div>RECEIVED By Olivia Yu at 1:31 pm, Aug 20, 2018</div>	
Describe Cause of Problem and Remedial Action Taken.* A contract water transfer company was in the process of filling the frac tanks, but became distracted and they over filled the tanks, allowing the release to occur.		
Describe Area Affected and Cleanup Action Taken.* Approximately 14.26 bbls of produced water was released in an area 40 feet by 80 feet and 0 bbls were recovered. An environmental contractor will be contacted to assist with delineation and remediation efforts.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>oy</i>	
Title: Admin Field Support	Approval Date: 8/20/2018	Expiration Date:
E-mail Address: denise.menoud@dmv.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/30/2018 Phone: 575-746-5544	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

* Attach Additional Sheets If Necessary

nOY1823248863

pOY1823249119

1RP-5161

23S - 33E - 22

Thistle Unit 111H

23S - 33E - 22
NENE

1

Lat: 32.296956° N
Long: 103.552832° W

14.26 BBLS REL - 0 BBLS REC

Thistle Unit 111H

Spill 7/30/18 14.26 BPW



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Menoud
Map is current as of: 30-Jul-2018



Miles

0 0.01 0.02 0.04 1:1,779