

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Gettysburg State Com #004H	Facility Type: Flowline	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-41929

### LOCATION OF RELEASE

Unit Letter B	Section 16	Township 23S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.3107987 Longitude -103.4721183 NAD83

### NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 8 bbl.	Volume Recovered: 0 bbl.
Source of Release: 3 <sup>rd</sup> Party	Date and Hour of Occurrence: August 20, 2018 12:30pm	Date and Hour of Discovery: August 20, 2018 12:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	<div><b>RECEIVED</b> By CHernandez at 7:24 am, Aug 22, 2018</div>	
Describe Cause of Problem and Remedial Action Taken.*		

The release was caused by a 3<sup>rd</sup> party cutting the flowline. Flowline has been repaired.

Describe Area Affected and Cleanup Action Taken.\*

The release was in the pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 8/22/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: August 21, 2018	Phone: 432-253-4513	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

\* Attach Additional Sheets If Necessary

1RP-5169

pCH1823428146

nCH1823427905