

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Steve McGlasson, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Kachina 8 Fed 1	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-025-30986

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	8	18S	33E	660	FNL	1830	FWL	Eddy

Latitude_32.7673416_ Longitude_103.6879425_ NAD83

NATURE OF RELEASE

Type of Release	Produced Water (PW)	Volume of Release	12.9BBLS PW	Volume Recovered	3.2BBLS PW
Source of Release	Hole in tank	Date and Hour of Occurrence	July 30, 2018 @ 11:30 AM MST	Date and Hour of Discovery	July 30, 2018 @ 11:30 AM MST
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Via C141		
By Whom?	Date and Hour N/A				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

RECEIVED


By CHernandez at 12:03 pm, Aug 23, 2018

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A hole was discovered in the bottom of the storage tank. The tank was isolated to prevent any further release. Repairs made.

Describe Area Affected and Cleanup Action Taken.*
Approximately 12.9bbbls of pw was released into secondary containment. Approximately 3.2bbbls of pw was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DeLaRosa		OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa		Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 8/23/2018	Expiration Date:	
E-mail Address: dana.delarosa@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date:	Phone: 575.748.3371		

* Attach Additional Sheets If Necessary

1RP-5170

NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.

nCH1823544435

pCH1823545076

Kachina 8 Fed 1

12.9BBLs PW_7.30.2018



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Dana DeLaRosa
Map is current as of: 01-Aug-2018



Miles
0 0.00 0.01 1:445

