

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company	Contact Merle Lewis, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371
Facility Name Thistle Unit 33 State 1 Battery(well on location Thistle Unit 1)	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-025-32138
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 33	Township 23S	Range 33E	Feet from the 790'	North/South Line FNL	Feet from the 1780'	East/West Line FWL	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	---------------

Latitude_32.2662888_ Longitude_103.5800247_ NAD83

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 1/2bbl	Volume Recovered 0bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence August 10, 2018 @ 4:31 AM	Date and Hour of Discovery August 10, 2018 @ 4:31 AM
Was Immediate Notice Given? <div><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required</div>	If YES, To Whom? Olivia Yu, OCD Chistina Hernandez, BLM	
By Whom? Brett Fulks, EHS Representative	Date and Hour August 11, 2018 @ 1:19 PM	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

RECEIVED

By CHernandez at 9:19 am, Aug 27, 2018

RECEIVED

By CHernandez at 9:19 am, Aug 27, 2018

Describe Cause of Problem and Remedial Action Taken.*

The Jal NM police department notified Devon that the battery was on fire due to a lightning strike. The Fire Department was able to extinguish the fire.

Describe Area Affected and Cleanup Action Taken.*

Approximately 1/2bbl produced water was released. This facility had mostly been emptied and was not active at the time of the strike. An Environmental contractor will be contacted to assist with further delineation and remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist: <i>EH</i>	
Title: Field Admin Support		Approval Date: 8/27/2018	Expiration Date:
E-mail Address: Sheila.Fisher@dvn.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/13/18	Phone: 575.748.1829	NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation.	

* Attach Additional Sheets If Necessary

1RP-5175

nCH1823931703

pCH1823932049