

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Merle Lewis, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Thistle Unit 118H	Facility Type	
Surface Owner State	Mineral Owner State	API No. 30-025-43451	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	34	23S	33E	621'	FSL	2199'	FWL	Lea

Latitude\_32.2556006\_ Longitude\_103.5616293\_ NAD83

### NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Fire	0	0
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Compressor	August 10, 2018 @ 5:00 AM	August 10, 2018 @ 5:00 AM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Olivia Yu, OCD Chistina Hernandez, BLM	
By Whom?	Date and Hour	
Brett Fuls, EHS Representative	August 11, 2018 @ 1:29 PM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

**RECEIVED**

**By CHernandez at 9:19 am, Aug 27, 2018**

Describe Cause of Problem and Remedial Action Taken.\*  
Lease Operator arrived on location and discovered a 2' flame coming from the top of the compressor on the blowdown line.

Describe Area Affected and Cleanup Action Taken.\*  
The flame went out on its own and no release was associated with the fire.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist: <i>SH</i>	
Title: Field Admin Support		Approval Date: 8/27/2018	Expiration Date:
E-mail Address: Sheila.Fisher@devon.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/14/18 Phone: 575.748.1829		NMAC 19.15.29 effective August 14, 2018. Complete release characterization before any significant remediation. Dated photo documentation of the fire site.	

\* Attach Additional Sheets If Necessary

1RP-5176

nCH1823935024

pCH1823939786