

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Company	Contact Callie Karrigan	
Address 5555 San Felipe St, Houston TX, 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)	
Facility Name Ballard DE Federal #2	Facility Type Oil Well	
Surface Owner Federal	Mineral Owner Federal	API No. 30-025-02465

### LOCATION OF RELEASE

Unit Letter C	Section 27	Township 20S	Range 43E	Feet from the 330	North/South Line North	Feet from the 2310	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude\_32.5504454\_\_\_\_\_ Longitude\_-103.5491486\_\_\_\_\_ NAD83

### NATURE OF RELEASE

Type of Release oil	Volume of Release 10bbls	Volume Recovered unknown
Source of Release flowline	Date and Hour of Occurrence 7/4/2017	Date and Hour of Discovery 7/4/2017
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*

Estimated spill volume of ten barrels coming from area around the wellhead and flowline. Cause was a roustabout crew that had been working on the pumping unit and failed to open the flowline when work was completed. Well has been shut in.

Describe Area Affected and Cleanup Action Taken.\*

Immediate actions taken at time of incident and remedial action outlined in closure report submitted to NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: Callie Karrigan

Printed Name: Callie Karrigan

Approved by Environmental Specialist:

Title: HES Professional

Approval Date:

9/17/2018

Expiration Date:

xx/xx/xxxx

E-mail Address: cnkarrigan@marathonoil.com

Conditions of Approval:

Date: 6/18/18

Phone: 405-202-1028

BLM approval

Attached ☐

\* Attach Additional Sheets If Necessary

1RP-4765

**APPROVED**

**By Olivia Yu at 11:26 am, Sep 17, 2018**