

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NOY1826745008
District RP	1RP-5198
Facility ID	
Application ID	pOY1826745215

Release Notification

Responsible Party

Responsible Party CHISHOLM ENERGY OPERATING, LLC	OGRID 372137
Contact Name TIM GREEN	Contact Telephone 432-413-9747
Contact email tgreen@chisholmenergy.com	Incident # (assigned by OCD)
Contact mailing address 801 CHERRY STREET, SUITE 1200-UNIT 20, FORT WORTH, TX 76102	

Location of Release Source

Latitude 32.71063 Longitude -103.68956
(NAD 83 in decimal degrees to 5 decimal places)

Site Name GAZELLE 32 SATE COM 2BS 1H / 2Y	Site Type WELL PAD LOCATION
Date Release Discovered 09/03/2018	API# (if applicable) 30-025-43906 / 30-025-44197

Unit Letter	Section	Township	Range	County
C	32	18S	33E	LEA

State minerals

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 290	Volume Recovered (bbls) 280
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release LIGHTNING STRIKE CAUSING FIRE

Incident ID	NOY1826745008
District RP	1RP-5198
Facility ID	
Application ID	pOY1826745215

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? FIRE, AND RELEASE OF OVER 25 BBLs
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? NO	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: JENNIFER ELROD	Title: SR. REGULATORY ANALYST
Signature: <u>Jennifer Elrod</u>	Date: 09/06/2018
email: jelrod@chisholmenergy.com	Telephone: 817-953-3728
OCD Only <div style="border: 1px solid black; padding: 5px; display: inline-block;"> RECEIVED By Olivia Yu at 12:23 pm, Sep 24, 2018 </div> Received by: _____ Date: _____	

From: Yu, Olivia, EMNRD
To: "Jennifer Elrod"; Mann, Ryan
Cc: Tim Green
Subject: RE: Gazelle 32 C-141
Date: Monday, September 24, 2018 12:47:00 PM
Attachments: 1RP5198_GAZELLE 32_C141_Part 1_09062018.pdf
image001.png

Ms. Elrod:

Thank you for the photos. Please note that dated, georeferenced photo documentation should be of the release point, verifying that the release has been contained.

Please be advised that

1. The initial portion of the C-141 form does not include the calculations to determine the release volume. Visual estimation is not sufficient nor adequate. Please submit measurements in volume estimation; including dimensions, soil parameters (porosity, texture, bulk density, etc).
2. The GPS coordinates provided must be of the release point. Unless the release was from the wellhead (e.g., stuffing box), do not use the wellhead latitude and longitude units.
3. Per 19.15.29.10 NMAC, a major release necessitates immediate notification to NMOCD Environmental Bureau chief, in addition to District office.
4. Per 19.15.29.13 NMAC, regulations of corresponding agencies supersede NMOCD's.

The 1RP for this incident is

5198	9/21/2018	A	Chisholm	Gazelle 32 State Com 2BS 1H/2Y	30-025- 43906	18S-33E- 32C	9/3/2018
-------------	-----------	---	----------	-----------------------------------	------------------	-----------------	----------

Please remember to include this 1RP identifier to all communications. Revised NMAC 19.15.29 was effective on August 14, 2018. Delineate and remediate per regulation. Mind the timelines for submittal of requisite information.

Please be advised that NMOCD recommends a completed site characterization/delineation report be reviewed or approved by NMOCD BEFORE any significant remediation work towards closure.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Jennifer Elrod <jelrod@chisholmenergy.com>
Sent: Friday, September 14, 2018 12:30 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Brown, Maxey G, EMNRD <MaxeyG.Brown@state.nm.us>
Cc: Tim Green <tgreen@chisholmenergy.com>
Subject: Gazelle 32 C-141

Olivia,
Here is the Part 1 of the C-141 and pictures showing location after the vacuum truck had been used.

Thanks,
Jennifer

Jennifer Elrod



801 Cherry St., Suite 1200-Unit 20

Fort Worth, TX 76102

Direct: 817-953-3728

Cell: 940-452-6214

Fax: 817-601-7551

From: Jennifer Elrod
To: [Yu, Olivia, EMNRD](#); [Brown, Maxey G, EMNRD](#)
Cc: [Tim Green](#)
Subject: Lightning Strike/Spill Gazelle 32 State Com 2BS 1H & 2Y Tank Battery
Date: Tuesday, September 4, 2018 11:35:35 AM
Attachments: image001.png

There was a lightning strike yesterday at the Gazelle 32 State Com 2BS 1H & 2Y tank battery (30-025-43906 & 30-025-44197).

There was a spill, I am working to get all the details down in report form for C-141.

I will send in all of the paperwork as soon as it is complete.

Jennifer Elrod



801 Cherry St., Suite 1200-Unit 20
Fort Worth, TX 76102
Direct: 817-953-3728
Cell: 940-452-6214
Fax: 817-601-7551



