Mr. Batt:

Notes

- Please remember to check surface and mineral ownerships upon submittal of a C-141 form to ensure that all corresponding agencies are informed concurrently. For this release, NMSLO is both the surface and minerals owner. NMSLO can verify.
- In order for the appropriate Responsible Party to be attributed, please provide an OGRID code. NMOCD databases indicate more than 1 OGRID available for Phillips 66. No need to resubmit, an email response suffices.

Please be advised that

- 1. The initial portion of the C-141 form does not include the calculations to determine the release volume. Visual estimation is not sufficient nor adequate. Please submit measurements in volume estimation; such as dimensions (L X W X depth of impact), soil parameters (porosity, texture, bulk density, soil moisture), meter readings, waste manifests, etc.
- 2. Dated, geo-referenced photo documentation for verification that the initial response activities have been employed to contain the release is requested.
- 3. Per 19.15.29.13 NMAC, regulations of corresponding agencies supersede NMOCD's.

The 1RP for this incident is

5217 10/1/2018 A Phillips 66 pipeline NM 28 East Glorietta 17S-35E-280 9/28/
--

Please remember to include this 1RP identifier to all communications. Revised NMAC 19.15.29 was effective on August 14, 2018. Delineate and remediate per regulation. Mind the timelines for submittal of requisite information.

Please be advised that NMOCD recommends a completed site characterization/delineation report be reviewed or approved by NMOCD BEFORE any significant remediation work towards closure.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Batt, Aly H <Aly.H.Batt@p66.com>
Sent: Saturday, September 29, 2018 10:06 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Gill, D. Clint Jr. <David.C.Gill@p66.com>; Hendrix, Brad A <Brad.A.Hendrix@p66.com>; Coffman, Keith K
<Keith.K.Coffman@p66.com>; Shepherd, Bill D <Bill.D.Shepherd@p66.com>; Batt, Aly H <Aly.H.Batt@p66.com>; Wilson, Stephanie D
<Stephanie.D.Wilson@p66.com>
Subject: [EXT] NM 28 East Glorietta

Good Morning Olivia

On 9/28/2018, due to unknown causes crude oil was released from a gathering pipeline onto the ground. The location of the release is: Latitude 32° 47' 59" N Longitude 103° 27' 45" W. P66 emergency response team traveled immediately to the release location. It was initially estimated to be 22 bbls.

P66 emergency response and field personnel completed the following field actions:

1-The source of the release has been stopped.

2-The impacted area has been secured to protect human health and the environment.

3-Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

4-All free liquids and recoverable materials have been removed and managed appropriately

On 9/29/2018 additional field information were available and the estimated release is 220 bbls.

A phone notification was made to Mr. Maxey Brown with OCD Hobbs District Office [(575) 370-3186] at 10:41 am 9/29/2018.

Please let me know if you have any more questions.

Aly Batt, PhD

Environmental Specialist | Phillips 66 Midstream

O: (832) 765-3651 2331 CityWest Blvd., 8th Floor N870-01| Houston, TX 77042

