From: Sheldon Hitchcock

To: Yu, Olivia, EMNRD; DeAnn Grant; Mann, Ryan

Cc: Hernandez, Christina, EMNRD; Ike Tavarez; Robert McNeill; Dakota Neel; Rebecca Haskell

Subject: RE: (C-141 Initial) Magnum Pronto State #006H (30-025-41977) 07-17-2018

Date: Wednesday, July 25, 2018 3:35:50 PM

Attachments: image003.png

Ms. Yu,

For clarification, the hole was in the bottom of the #4 tank. Yes there is a liner underneath the tanks. Please let me know if you have any other questions.

Thank you,

Sheldon L. Hitchcock
HSE Coordinator
COG Operating LLC

2407 Pecos Avenue | Artesia, NM 88210 Cell: 575-703-6475 | Office: 575-746-2010

slhitchcock@concho.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]

Sent: Friday, July 20, 2018 8:19 AM **To:** DeAnn Grant; Mann, Ryan

Cc: Hernandez, Christina, EMNRD; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell

Subject: [External] RE: (C-141 Initial) Magnum Pronto State #006H (30-025-41977) 07-17-2018

**** External email. Use caution. ****

Good morning Ms. Haskell:

Several questions for clarification: Where was the hole on the oil tank? Is there a liner underneath the tanks?

Photo documentation of the area around the affected tank, as well as the location of the hole on the tank is required. A liner integrity statement for verification of the lined facility also is required.

The 1RP for this incident is

				Magnum Pronto State Com			
5130	7/20/2018	Α	COG	#6H	30-025-41977	19S-32E-32D	7/17/2018

Please remember to include this 1RP identifier to all communications.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, July 19, 2018 9:49 AM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us >; Mann, Ryan < rmann@slo.state.nm.us >

 $\begin{tabular}{ll} \textbf{Cc:} Hernandez, Christina, EMNRD < & Christina. Hernandez@state.nm.us \\ & (EMCNeill@concho.com) \\$

<RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>

Subject: (C-141 Initial) Magnum Pronto State #006H (30-025-41977) 07-17-2018

Ms. Yu/Mr. Mann,

Please find the attached Initial C-141 for your consideration. If you have any questions or concerns please contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant
agrant@concho.com
COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.