District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural **Resources** Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Incident ID	nCH1827843022
District RP	1RP-5221
Facility ID	
Application ID	_pCH1827843284

Release Notification

Responsible Party

Responsible Party Devon Energy Production Company	OGRID	_
Contact Name Brett Fulks, EHS Professional	Contact Telephone 575-748-3371	
Contact email Brett.Fulks@dvn.com Incident # (assigned by OCD)		
Contact mailing address 6488 Seven Rivers Hwy Artesia	a, NM 88210	

Location of Release Source

Latitude 32.311578

Longitude -103.566558 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Black Mamba 15 State Com 2H CTB	Site Type Central Tank Battery
Date Release Discovered August 31, 2018	API# (if applicable) 30-025-40173

Unit Letter	Section	Township	Range	County
D	1	23S	33E	Lea

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (bbls) 144bbls	Volume Recovered (bbls) 144bbls
Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	Yes No
Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (Mcf)	Volume Recovered (Mcf)
Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
r line inside lined containment developed a hole causing were shut in and the line was isolated to stop the release	a produced water release inside lined containment. All
	Volume Released (bbls) 144bbls Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l? Volume Released (bbls) Volume Released (bbls) Volume Released (Mcf) Volume/Weight Released (provide units) or line inside lined containment developed a hole causing

Form C-141 Page 2 State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsible party consider this a major release? Release was over 25bbls.
Yes No	
If YES, was immediate n Yes by Brett Fulks, EHS R on September 1, 2018 @ 2	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? epresentative to Jim Griswold, EMNRD; Ryan Mann, SLO; Christina Hernandez, EMNRD & Olivia Yu, EMNRD 2:04 PM via email.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Sheila Fisher	Title: Administrative Assistant
Signature: Thile Hohn	
email: Sheila.Fisher@dvn.com	Telephone: 575-748-3371
	-
OCD Only RECEIVED	
Received by: By CHernandez at 3:50 pm, Feb 0	08, 2019

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?		
Did this release impact groundwater or surface water?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🗌 No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🗌 No	
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🗌 No	
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🗌 No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	Yes No	
Are the lateral extents of the release within a 100-year floodplain?		
Did the release impact areas not on an exploration, development, production, or storage site?	Yes No	

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Report Checklist: Each of the following items must be included in the report.	
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and mo Field data	nitoring wells.
 Data table of soil contaminant concentration data Depth to water determination 	
Determination of water sources and significant watercourses within ½-mile of the lateral extents of the r	elease
Photographs including date and GIS information	
Topographic/Aerial maps Laboratory data including chain of custody	
 Determination of water sources and significant watercourses within ½-mile of the lateral extents of the results of excavation logs Photographs including date and GIS information Topographic/Aerial maps 	elease

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Form C-141	State of New Mexico	
Page 4	Oil Conservation Division	Incident ID
	On Conservation Division	District RP
		Facility ID
		Application ID
regulations all operators an public health or the enviro failed to adequately invest	re required to report and/or file certain release notif poment. The acceptance of a C-141 report by the Out tigate and remediate contamination that pose a threa	best of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
Printed Name:		Title:
Signature:		Date:
email:		Telephone:
OCD Only		
Received by:		Date:

Form C-141 Page 5

OCD Only

Approved

Signature:

State of New Mexico Oil Conservation Division

Received by: _____ Date: _____

Approved with Attached Conditions of Approval

Incident ID	
District RP	
Facility ID	<u>_</u>
Application ID	

Deferral Approved

Remediation Plan

Remediation Plan Checklist: Each of the following items must be included in the plan.		
 Detailed description of proposed remediation technique Scaled sitemap with GPS coordinates showing delineation points Estimated volume of material to be remediated Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required) 		
Deferred Dequests Only Each of the following items must be cont		
Deferral Requests Only: Each of the following items must be confirmed as part of any request for deferral of remediation.		
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.		
Extents of contamination must be fully delineated.		
Contamination does not cause an imminent risk to human health, the environment, or groundwater.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	

Date:

Denied

Form C-141 Page 6 State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
<u>OCD OIIIY</u>		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	