Form C-141 Page 6

State of New Mexico Oil Conservation Division

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
Photographs of the remediated site prior to backfill or photos of must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office	
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
☐ Description of remediation activities		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of a	C-141 report does not relieve the operator of responsibility for ions. The responsible party acknowledges they must substantially ditions that existed prior to the release or their final land use in	
Printed Name:	Title:	
Signature:	Date:	
email:	Telephone:	
OCD Only		
Received by:	Date:	
Printed Name:		
_		