

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: STRATOSPHERE 36 STATE COM #005H	Facility Type: Battery
Surface Owner: Fee	Mineral Owner: State
API No.: 30-025-42036	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	36	20S	34E	190	North	2200	West	Lea

Latitude: 32.5363083 Longitude: -103.5151062 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15.5 bbls PW	Volume Recovered: 15 bbls PW
Source of Release: Fire tube	Date and Hour of Occurrence: 1/5/2018	Date and Hour of Discovery: 1/5/2018 4:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 4:08 pm, Jan 08, 2018

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the fire tube. The fire tube will be replaced.

Describe Area Affected and Cleanup Action Taken.*

The release remained within the lined containment. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

ey

Signature:

Printed Name: Dakota Neel

Title: HSE Coordinator

Approval Date: **1/8/2018**

Expiration Date:

E-mail Address dneel2@concho.com

Conditions of Approval:

Attached ☐

Date: 1/8/2018

Phone: 575-746-2010

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

nOY1800858320

* Attach Additional Sheets If Necessary